
INSTALLATION INSTRUCTIONS #TAM-U01 AIR MANIFOLD U-JOINT REPLACEMENT KIT

INTRODUCTION: The Air Manifold U-joint replacement kit includes a U-joint permanently affixed to the sliding portion of the lower arm. U-joint replacement requires disassembly of the lower arm of the TORQ-ARM™.


WARNING

Turn off compressed air supply to TORQ-ARM™ prior to removing tool or disconnecting air line. Failure to do so could result in damage to equipment or personal injury.




U-JOINT INSTALLATION

- 1. Turn off air supply to TORQ-ARM™.
- 2. Remove portable tool from U-joint. See Fig 2.
- 3. Disconnect air line from U-joint. See Fig 2.
- 4. Disconnect safety clip on balancer cable from slide arm. See Fig 2.



- Remove lock nuts and flat washers from three bolts thru lower arm. Carefully remove bolts and flat washers, allowing slide arm and U-joint to drop out of slide arm assembly. Do not lose spacers on bolts. See Fig 3.
- 6. Twist right hand (nut side) arm back to allow installation of new slide arm and U-joint. See Fig 2.
- Insert two lower bolts and flat washers into left hand arm. Bolts should extend thru arm 3/8" (thickness of slider arm or length of spacers). See Fig 3.



- 8. Place spacers on bolts. See Fig 3.
- Position new slide arm on spacers. Arm must be positioned with cable hole near top surface and with air fitting hole in side of manifold facing rear. See Fig 1.
- Twist right hand arm forward and align with bolts. Make sure spacers are on bolts, then push bolts thru arm.
- 11. Insert third bolt and washer with spacer between arm sections. Place hose clamp and flat washer on bolt and secure with lock nut.
- 12. Place flat washers and lock nuts onto lower two bolts. Tighten all three nuts.
- 13. Test slide action. Slightly loosen lock nuts if necessary.
- 14. Reattach balance cable safety clip, air line and tool.
- 15. Turn on compressed air and test for leaks.



Workplace Solutions

P.O. Box 26 • 600 South Clark St. Mayville, WI 53050 Phone 920–387–5195

Printed in USA Bulletin No. 62527801.a