
SINGLE COLUMN WORKSTRATION ASSEMBLY GUIDE





HAED BOOM

Horizontal rail

may be mounted

on top of or

butting up to

vertical column.

1- ALIGN parts in order of assembly.

as desired. **3-TIGHTEN** bolts, clamping parts to

rails.

2-SET (position) parts

Add attachments to suit.

See TYPICAL ASSEMBLY PROCEDURES on back of sheet.


Workplace Solutions


#WS50-UF30 &


WS50-UF36 LEG BASE


Fits most benches

Workstation kit assembly requires two wrenches or a socket set (sizes shown on reverse side), tape measure, and level. First, securely mount base to bench. Second, assemble workstation to base. Components must be assembled in proper order (1-ALIGN), properly positioned (2-SET) and clamped securely in place (3-TIGHTEN). Refer to picture of unit at left and typical assembly procedure on reverse side. After assembly, adjust components to suit.










Hubbell Workplace Solutions



TYPICAL ASSEMBLY

With arm

SWING BOOM

CAP

FIXED

HOOK

TYPICAL ASSEMBLY PROCEDURES

